

This Information Is Provided By
CBTricks.com

Cobra 29 (23Ch) Technical Bulletin 204

Liability of damages to any equipment is the sole responsibility of the user! Downloading, viewing, or using any information provided on these pages automatically accepts the user to the terms of this agreement!

Modifications are provided for information purposes only!

Supporters of CBTricks.com paid for the hosting so you would have this file.

CBTricks.com is a non-commercial personal website was created to help promote the exchange of service, modification, technically oriented information, and historical information aimed at the Citizens Band, GMRS (CB "A" Band), MURS, Amateur Radios and RF Amps.

CBTricks.com is not sponsored by or connected to any Retailer, Radio, Antenna Manufacturer or Amp Manufacturer, or affiliated with any site links shown in the links database. The use of product or company names on my web site is not endorsement of that product or company.

The site is supported with donations from users, friends and selling of the Site Supporters DVD's to cover some of the costs of having this website on the Internet instead of relying on banner ads, pop-up ads, commercial links, etc. Thus I do not accept advertising banners or pop-up/pop-under advertising or other marketing/sales links or gimmicks on my website.

ALL the money from donations is used for CBTricks.com I didn't do all the work to make money (I have a day job). This work was not done for someone else to make money also, for example the ebay CD sellers.

All Trademarks, Logos, and Brand Names are the property of their respective owners.

This information is not provided by, or affiliated in any way with any radio or antenna Manufacturers.

Thank you for any support you can give.

For information on how to Support CBTricks.com

<http://www.cbtricks.com/support/>

DYNASCAN SERVICE OPERATIONS

Cobra Communications

COBRA TECHNICAL BULLETIN

- SUBJECT: Green modulation light on Cobra 29.
- PROBLEM: Complaints from the field indicate the modulation light lights dim.
- SOLUTION: To brighten the light so it is proportioned to the percent of modulation change C-109 from 5 pf (Dynascan part number 020-109-9-010) to 10 pf (Dynascan part number 020-109-9-012).
- LOCATION: C-109 is parallel to the current control coil L-13 on component side of board.
- NOTE: The improvement is done under warranty during the warranty period only.

DDW/pc
6/76
#204