

This Information Is Provided By
CBTricks.com

Cobra 45 XLR Technical Bulletin 1220

Liability of damages to any equipment is the sole responsibility of the user! Downloading, viewing, or using any information provided on these pages automatically accepts the user to the terms of this agreement!

Modifications are provided for information purposes only!

Supporters of CBTricks.com paid for the hosting so you would have this file.

CBTricks.com is a non-commercial personal website was created to help promote the exchange of service, modification, technically oriented information, and historical information aimed at the Citizens Band, GMRS (CB "A" Band), MURS, Amateur Radios and RF Amps.

CBTricks.com is not sponsored by or connected to any Retailer, Radio, Antenna Manufacturer or Amp Manufacturer, or affiliated with any site links shown in the links database. The use of product or company names on my web site is not endorsement of that product or company.

The site is supported with donations from users, friends and selling of the Site Supporters DVD's to cover some of the costs of having this website on the Internet instead of relying on banner ads, pop-up ads, commercial links, etc. Thus I do not accept advertising banners or pop-up/pop-under advertising or other marketing/sales links or gimmicks on my website.

ALL the money from donations is used for CBTricks.com I didn't do all the work to make money (I have a day job). This work was not done for someone else to make money also, for example the ebay CD sellers.

All Trademarks, Logos, and Brand Names are the property of their respective owners.

This information is not provided by, or affiliated in any way with any radio or antenna Manufacturers.

Thank you for any support you can give.

For information on how to Support CBTricks.com

<http://www.cbtricks.com/support/>



SERVICE OPERATIONS GROUP

Cobra Communications

COBRA FIELD BULLETIN - 1220

SYMPTOM I: Popping noise in CB position of 45XLR.

CAUSE: When a strong signal such as ignition noise is fed into receiver, TR-104 becomes unstable and breaks into intermittent oscillation.

CORRECTIVE ACTION:

Cut copper foil between collector or TR-104 and L-105 I.F. coil. Place a 1000 ohm 5% 1/8 watt carbon film resistor, Part No, 002-108-5-102 across cut foil.

SYMPTOM. II: FM, CB audio mix in moni position complaints.

CAUSE: Customers receiving area might not produce proper amount of audio mix in moni position.

CORRECTIVE ACTION:

Change value of R-131 (5.6K) from 0 to 10K to suit customers preference.

This modification is performed on all serial number radios during warranty period when the customer complains.

DDW/pc
#1220
10/77