



JP101 A R112 100K
 JP102 B R113 100K
 JP103 C R114 100K
 JP104 D R115 100K
 JP105 E R116 100K
 JP106 F R117 100K
 JP107 G R118 100K
 JP108 H R119 100K

PLL4[4] FSYB
 PLL4[8] FSY1
 PLL4[4] SDA1A
 PLL4[4] SCLK

P13_4 (FSYB)
 P13_5 (FSY1)
 P13_6 (SDA1)
 P13_7 (SCLK)
 VL4
 P12_2
 P12_3
 VL3
 P12_3
 VL2
 P12_3
 VL1
 P0_0 (JP8)
 P0_1 (JP7)
 P0_2 (JP6)
 P0_3 (JP5)
 P0_4 (JP4)
 P0_5 (JP3)
 P0_6 (JP2)
 P0_7 (JP1)
 P1_0
 P1_1
 P1_2
 AN15 (SRF)
 P1_4
 P1_5
 P1_6 (COMP)
 P1_7
 P2_1
 P2_2
 P2_3
 P2_4
 P2_5
 P2_6
 P2_7
 P2_8
 P2_9
 P2_10

MANNA7C1 COMP

JP1 Band plan 1
 JP2 Band plan 2
 JP3 Band plan 3
 JP4 Band plan 4
 JP5 Band plan 5
 JP6 Band plan 6
 JP7 Band plan 7
 JP8 Band plan 8

	A (JP101)	B (JP102)	C (JP103)	D (JP104)	E (JP105)	F (JP106)	G (JP107)	H (JP108)
DXSR8	Solder	Solder	NC	NC	Solder	NC	NC	NC
DXSR8 T	NC	NC	NC	Solder	NC	NC	NC	NC
DXSR8 E	NC	NC	NC	NC	Solder	NC	NC	NC