

# **WARNING**

The FTM-350 has a problem with Weather channels when all but one Weather channel has the Skip option set to Skip. This would be logical programming since you generally want to use only the one Weather Channel in your area.

While scanning memory channels with Weather Alert engaged, when the radio attempts to access the Weather Channels, it will "freeze" on that one channel.

Nothing can be done from the face of the radio to restore it to normal operation. Repair to the radio will be required. Contact Yaesu Tech support for details.  
714-827-7600

While this condition can be created easily from the ADMS programmer, the actions of the radio are not a result of its being programmed with the software. The same thing will happen if you set the options from the face of the radio.

*Protect your radio, leave the Skip option for  
TWO Weather Channels set to OFF.*